GSI Drying Systems Electronics Pricing

Part Number	List Price 2-26-04	Core Net Credit	Rebuild List Price	Description
EMCS PORTABLE DRYER & TOP DRY				
D03-0119	$1,099.00	*	$555.00	EMCS Display Module
D03-0120	$718.00	$61.00	$235.00	EMCS CPU Module
D03-0121	$1,990.00	$61.00	$552.00	EMCS I/O Module
D03-0189	$53.00	NA	NA	EMCS Cable between the I/O and CPU boards
D03-0116	$284.00	NA	NA	EMCS Touch Panel - Dryer or Top Dry
D03-0123	$549.00	NA	NA	EMCS Touch Panel - Batch Dryer only
D03-0045	$140.00	NA	NA	EMCS Grain Temperature RTD Sensor - Portable Dryer and Topdry
COMPETITOR DRYER				
D03-0275B	$751.00	$46.00	$523.00	SR. 2000 CPU w/ Batch Decal
D03-0275D	$751.00	$46.00	$523.00	SR. 2000 CPU w/ Competitor Dryer Continuous Decal
D03-0276	$591.00	$40.00	$297.00	SR. 2000 I/O Board for Competitor Dryers only - Batch and Continuous
D03-0555	$33.00	NA	NA	Competitor Cable (I/O to Display - Pin to Pin)
HF-7236	$45.00	NA	NA	SR. 2000 Thermister Sensor - Bolt type for all Plenums and T.D. Grain
D03-0258	$31.00	NA	NA	SR. 2000 Thermister Sensor - Competitor Grain Temp.
BATCH TOP DRY AND FAN & HEATER BOARDS				
HF-7276T	$731.00	$67.00	$495.00	SR. 2000 Batch Top Dry Heater Board w/ Decal - Batch
HF-7276H	$731.00	$67.00	$495.00	SR. 2000 Fan Heater Board w/ Decal
NETWORK PORTABLE DRYER & TOP DRY				
D03-0593	$1,740.00	$94.00	$870.00	Network Dryer or Top Dry Display Board
D03-0587	$1,877.00	$104.00	$938.00	Network Dryer I/O Board - Dryer or Autoflow (Specify Software version)
HF-7276N	$731.00	$67.00	$495.00	SR. 2000 Network Dryer Burner w/ Decal
HF-7276A	$731.00	$67.00	$495.00	SR. 2000 Autoflow Top Dry w/ Decal
D03-0340-CBL	$34.00	NA	NA	Network Cable for D03-0340 (Display to Speed Pot - Not Pin to Pin)
HF-7236	$45.00	NA	NA	SR. 2000 Thermister Sensor (Bolt type for all Plenums and T.D. Grain)
TAF-6150	$429.00	NA	NA	Touch Panel Network Autoflow and Portable Dryer
FENWALL AND OTHER FLAME SENSING COMPONENTS				
[1]HF-7318	$335.00	$24.00	$166.00	[1]Deluxe Heater Board
HF-4624-R	$336.00			Fenwal Ignition Board
THH-4179	$35.00			Flame Sensor 6" long rod for use with Fenwall and all newer ignitions.
TF-1558	$92.00			Igniter Assembly - Complete w/ boots, Wires, Rods and Brackets
CD-0238	$6.38			Igniter Rods - two will replace existing igniter with old wires and bracets
HH-1650	$25.00			Spark Plug for Heaters: Spark Plug nut - HF-1810
[2]HF-7275	$179.00			[2]94-97 Flame Probe Sensor (New Black Box) Module - Replaces HH-7034 (Old Black Box)
[3]HF-7100	$183.00			[3]89-96 Smart Heater Board
HF-7356	$84.00			Flame Probe Proving Terminal Strip for "Standard" Heaters
SCR BOARDS & COMPONENTS				
D03-0104	$206.00			Old Style SCR Drive Board with Fuse top. (Do not use on a Network Dryer)
[4]D03-0679	$607.00			[4]Network SCR Drive Board Complete.
[4]D03-0592	$412.00			[4]Network SCR Drive Board Top. (Use together with D03-0104)
D03-0039	$4.39			SCR Resistor for 1/3 hp drive motor
D33-0001	$4.60			SCR Resistor for 3/4 hp drive motor
FLASH PROGRAMING ITEMS FOR YOUR PALM PILOT				
D03-0695	$27.00			Dongle for use between Palm Pilot Hotsync Cable and our Boards
D01-1771	$139.00			SR. 2000 Programming Cable for use between Dongle and SR. 2000 Board
D03-0709	$5.75			Software - Palm Conduit & flash files. (This can be downloaded from the GSI Website)
You can buy a Palm locally. See further information on our web site at http://www.grainsystems.com/gsi/progs/page11.html				

* There is no core value to these displays as they can not be repaired. We do have returns once in a while at a Rebuild Price.

[1]HF-7318 will directly replace HF-7100. (1) TFH-2021 Neon light $5.06 is required in every case.

(1) THH-4179 Flame Sensor $35.00 and(1) CD-0187 Flame Sensor Bracket $3.09 are required on all units that have mechanical flame sensing.

[2]HH-7034 should be replaced with HF-7275

[3]When replacing a 89-92 HF-7100 board a HF-7203 Relay $29.00 is required.

[4]Make sure you only use this special Network SCR top board as using a D03-0104 will destroy both the Display and I/O boards.

1. Net Core Credit will be credited when Circuit Board is returned in repairable condition. No Discounts apply to Core Credits.

2. Rebuilt Boards may not be available due to supply of cores returned

Add "C" to part number for Core Value circuit boards. Add "R" to part number for rebuilt circuit boards

5/27/2004