PNEG-455


Field drill hole
in sidewall for cable
passthrough.
Grommet clips
Field drill hole
in sidewall for cable
passthrough.
Rubber bulb seal strip
to seal between box & sidewall
Removeable cover plate
OUTER GRAIN SAMPLER
BOX ASSEMBLY
Attach with 3 #10
self-drilling screws
(S=280)
3.1/4" I.D. PVC Pipe
(Optional from G.S.I.)
Cables
PVC SLIDE VALVE
GRAIN SAMPLER
DUMP CHUTE ASSEMBLY
INNER GRAIN SAMPLER
SPLITER ASSEMBLY
Field drill sidewall to
match box mounting holes.
Field cut hole in sidewall
for inner spliter assembly
chute to pass through.
Attach with 3 #10
self-drilling screws
(S-280)