

THE GSI GROUP



Informational Update

Recommended Product Update:

GSI Competitor Dryers and Topdry equipment have a jumper wire that when moved will increase protection to each of the computer circuit boards. D03-0275 & HF-7276 have a jumper wire in a position that allows the computer to work properly, but when this jumper wire is moved it adds protection to the circuits on the board. Leaving the jumper wire in it's present location will not have any affect to the equipment's normal operation, but when the jumper is moved the amount of protection to the board is increased.

Enclosed is a .pdf file that should will show the jumper in it's present location and repositioning it to it's new location. The update is for added circuit protection of the computer boards only. You will not see any difference in the operation of the equipment.

You can make this change on any dryers from the beginning of the Competitor series in 1993 to the present, and all Topdry equipment that uses this board. New dryers (After June of 2004) coming out of the factory already have this change made.

Thanks

Virgil Rhodes
Dryer Division Manager
106 Marshall Drive
Newton, Illinois 62448
Phone: 618-783-3138
Fax: 618-783-8227
virgilr@grainsystems.com