2007 GSI Drying Systems Electronics Pricing

 1			Rebuilt List	ectionics Fricing				
Part Number	10-3-07**	Credit		Description				
	•		Red Prices U	navailable due to no cores returned - Green Prices Available Core				
EMCS PORT. DRYER & TOP DRY			Net good against New or Rebuilt					
D03-0119	\$999.00	*	\$679.00	\$679.00 EMCS Display Module				
D03-0120	\$499.00	\$50.00	\$399.00	EMCS CPU Module				
D03-0121	\$999.00	\$100.00	\$679.00	EMCS I/O Module				
D03-0122	\$2,499.00	NA	NA	Above Three Boards as a Kit				
D03-0189	\$127.00	NA	NA	EMCS Cable between the I/O and CPU boards				
D03-0116	\$298.33	NA	NA	EMCS Touch Panel - Dryer or Top Dry				
D03-0123	\$376.00	NA		EMCS Touch Panel - Batch Dryer only				
D03-0045	\$147.00	NA		EMCS Grain Temperature RTD Sensor - Portable Dryer and Topdry				
D03-0227	\$221.00	NA	NA	Power Supply 1.7AMP 12VDC Powerone #HB-1.7-A OR CONDORHB12-1.7-A+				
COMPETITOR DI								
D03-0275B	\$725.00	\$72.00	\$490.00	SR. 2000 CPU w/ Competitor Batch Decal				
D03-0275D	\$725.00	\$72.00		SR. 2000 CPU w/ Competitor Dryer Continuous Decal				
D03-0276	\$575.00	\$57.00		I/O Board for Competitor Dryers only - Batch and Cont.				
D03-0555	\$31.50	NA		Competitor Cable (I/O to Display - Pin to Pin)				
HF-7236	\$47.45	NA		Thermister Sensor - Bolt type (For all Plenums except EMCS) & T.D. Grain				
D03-0258	\$32.55	NA NA		Thermister Sensor - Boit type (For all Flerialitis except EMOS) & 1.B. Staill Thermister Sensor - Grain Temp (All but EMCS)				
BATCH TOP DRY				Theimister derisor - Grain Temp (All but Livido)				
HF-7276T	\$725.00			SR. 2000 Batch Top Dry Heater Board w/ Decal - Batch				
HF-7276H	\$725.00	\$72.00		SR. 2000 Fan Heater Board w/ Decal				
NETWORK PORT				SR. 2000 Fall fleater board w/ Decal				
				Natural Prior or Top Dry Dioplay Board				
D03-0593	\$1,822.00			Network Dryer or Top Dry Display Board				
D03-0587	\$1,971.00			Network Dryer I/O Board - Dryer or AutoFlow (Specify Software version)				
HF-7276N	\$725.00	\$72.00		SR. 2000 Network Dryer Burner w/ Decal				
HF-7276A	\$725.00	\$72.00		SR. 2000 AutoFlow Top Dry w/ Decal				
D03-0340-CBL	\$31.00	NA		Network Cable for D03-0340 (Display to Speed Pot - Not Pin to Pin)				
HF-7236	\$47.45	NA		Thermister Sensor - Bolt type (For all Plenums except EMCS) & T.D. Grain				
D03-0258	\$32.55	NA		Thermister Sensor - Grain Temp (All but EMCS)				
TAF-6150	\$318.00	NA		Touch Panel Network AutoFlow and Portable Dryer				
MM-VBS	\$45.15	NA		NA Moisture Control Sensing Auger Repair Kit. V-Belt, Bushing & Sheeve included.				
				nd each Decal & a Palm to download software covers all GSI Models				
D03-0275	\$700.00			SR. 2000 CPU w/o Decal Used on Competitor Cont. & Batch Dryers				
HF-7276	\$700.00	\$72.00		SR. 2000 CPU w/o Decal Used on TopDry Batch, Autoflow & Network Portables				
DC-123	\$25.00	NA		Decal for Competitor Continuous Flow Dryer				
DC-1262	\$30.79	NA		Decal for Competitor Batch Dryer				
DC-1513	\$25.00	Na		Decal for Network Fan & Heater for Network Portable Dryer				
DC-844	\$25.00	Na		Decal for Series 2000 TopDry Batch and Autoflow Heater Units				
DC-1437	\$40.50	Na	Na	Decal for Series 2000 Heater for Bin Drying Fans				
VISION DRYER								
D03-0763-ASY	\$3,616.00	NA		Touch Screen & Computer Assembly				
D03-0753DB9	?	NA		Touch Control CBL DB9F to DB9F (In Parts Manual)				
D03-0764	\$236.00	NA		Touch Control Display Internal Power Control Board Assembly				
D03-A753TCBL	?	NA		Touch Screen CBL 4-WR MOD. FR 3M				
D03-A753TUSB	?	NA	NA	Touch Screen CABLE USB MOD 37.5" (In Parts Manual)				
D03-0723-C	\$625.00	NA		Touch Control Display I/O PCB Comp				
D03-0725-C	\$473.00	NA	NA	Vision Moisture Board Assembly				
D03-0730-C	\$782.00	NA	NA	Dryer FAN/HTR Board Vision				
D03-0736-C	\$1,208.00	NA		Dryer I/O PCB ASM COMP Vision (In Parts Manual)				
D03-0742-C	\$157.50			Dryer Power Supply, ASM VIS/DRT (In Parts Manual)				
D03-0754-C	\$166.50			Touch Control 5VDC Power Supply (In Parts Manual)				
HF-7236	\$47.45	NA		Thermister Sensor - Bolt type (For all Plenums except EMCS) & T.D. Grain				
D03-0258	\$32.55	NA		Thermister Sensor - Grain Temp (All but EMCS)				
E300-1009	\$2.06	NA		Fuse 1 amp 5x20				
F000-1003	¥•							
E300-1009 E300-1017	\$0.77	NA	NΑ	Fuse 2 amp 5x20				

^{*} There is no core value to these displays as they can not be repaired. We do have returns once in a while at a Rebuild Price.

^{1.} Net Core Credit will be credited when Circuit Board is returned in repairable condition. No Discounts apply to Core Credits.

^{2.} These Rebuilt Boards are not presently available due to no cores returned. PLEASE return all usable cores.

Add "C" to part number for Core Value Circuit Boards. Add "R" to part number for most Rebuilt Circuit Boards (Verify when you order)

^{**} Prices Subject to change at any time

	List Price	Core Net Rebuilt List						
Part Number	9-1-06	Credit 9-1-06 Description						
METERING ROLI	LSENSOR	FOR ALL MODELS						
D01-0527	\$54.60	NA NA SCR Meter Roll Speed Sensor						
FENWALL BOAR	FENWALL BOARD, FLAME SENSING COMPONENTS & MISC COMPONENTS							
¹HF-7318	\$280.00	\$25.00 \$174.00 Deluxe Heater Board						
HF-4624-R	\$353.00	3						
HH-6425		5 Old Fenwall Board Circuit Breaker (Reset Button). Not used since about 1997						
THH-4179		5 Flame Sensor 6" long rod for use with Fenwall and all newer ignitions.						
THH-4182		55 Flame Sensor Kit. Includes Sensor & Mounting Bracket.						
TF-1558		\$81.00 Igniter Assembly - Complete w/ boots, Wires, Rods and Brackets for all GSI Burners						
TF-1558-CENT		203.00 Igniter Assembly - Complete w/ boots, Wires, Rods and Brackets for Centrifugal Fans						
TF-1558-DT		\$81.00 Igniter Assembly - Complete w/ boots, Wires, Rods and Brackets for DriTek & DT+ FFI Dryers						
TF-1558-V		81.00 Igniter Assembly - Complete w/boots, Wires, Rods and Brackets for Vision Dryers						
CD-0238		.59 Igniter Rods - Use two to replace existing igniter rods while using old wires and brackets						
HH-1650		\$26.25 Spark Plug for Heaters: Spark Plug nut - HF-1810						
HH-3977		GSI Flame Probe						
026-1023-6		0 FFI Flame Probe. Limited quanities. Will be replaced by HH-3977 & a adaptor sleeve.						
² HF-7275		6.00 1994-1997 Flame Probe Sensor Module - Replaces HH-7034 (Old Black Box)						
³ HF-7100	¥	92.00 ³ 1989-1996 Smart Heater Board						
HF-7356	\$88.20	\$88.20 Flame Probe Proving Terminal Strip for "Standard" Heaters						
SCR BOARDS & DISCHARGE COMPONENTS								
D03-0104-1/3		SCR Drive Board with Fuse top for 1/3 HP. All Models except Network (Do not use on a Network Dryer)						
D03-0104-3/4		SCR Drive Board with Fuse top for 3/4 HP. All Models except Network (Do not use on a Network Dryer)						
⁴ D03-0679		549.00 Network SCR Drive Board Complete. Does NOT include the Resistor.						
⁴D03-0592		⁴Network SCR Drive Board Top Only.						
D03-0039		SCR Resistor for 1/3 hp drive motor. Works on all SCR Boards.						
D33-0001		SCR Resistor for 3/4 hp drive motor						
D01-1216		Discharge Mercury Switch Components. Mercury Sw., Mounting Plate, Condulet box, cord & hardware						
FLASH PROGRAMMING ITEMS FOR YOUR PALM PILOT								
D03-0695		Dongle for use between Palm Pilot Hotsync Cable and our Boards						
D01-1771		SR. 2000 Programming Cable for use between Dongle and SR. 2000 Board						
D03-0709		Software - Palm Conduit & flash files. (This can be downloaded from the GSI Website)						
You can buy a Palm locally. See further information on our web site at http://www.grainsystems.com/gsi/progs/page11.html								

VIS-LCB-DSP	\$6.345.00	NA	NA Vision Dealer Display Demo Box	
	¥ -,	3 33 3	· · · · · · · · · · · · · · · · · · ·	

If you use either of the D03-0104 (1/3 or 3/4) You will Destroy the Network I/O board. Do Not Use These Boards on a Network Dryer.

¹HF-7318 will directly replace HF-7100. (1) TFH-2021 Neon light \$5.85 is required in every case.

⁽¹⁾ THH-4179 Flame Sensor \$40.95 and (1) CD-0187 Flame Sensor Bracket \$3.24 are required on all units that have mechanical flame sensing.

²HH-7034 should be replaced with HF-7275

³When replacing a **1989-1992 HF-7100** board a **HF-7203** Relay **\$30.45** is required.

⁴Make sure you only use this special Network SCR top board as using a **D03-0104** will destroy both the Network Display and I/O boards.

^{1.} Net Core Credit will be credited when Circuit Board is returned in repairable condition. No Discounts apply to Core Credits.

Add "C" to part number for Core Value Circuit Boards. Add "R" to part number for most Rebuilt Circuit Boards (Verify when you order)