

DMC#	PNEG#	Description
		DOMESTIC
Pneg-1128	Pneg-1128	Chain Loop System w/out Controls
302L0009	Pneg-1137	Bin Level-Auto Cntrl Grain Spred Model 918 & 936
602L145	Pneg-1138	Combine Calc-U-Dri II w/ Averaging
3040004	Pneg-1139	Econo-Mizer Grain Spreaders Models 982, 986, 996
OMCCD0590	Pneg-1140	Combine Calc-U-Dri I
5047040	Pneg-1141	Calc-U-Dri Printer
	Pneg-1142	Calc-U-Dri Model 25
	Pneg-1143	Calc-U-Dri Models 40 & 60
	Pneg-1144	Calc-U-Dri Models 75 & 100
205N0048	Pneg-1145	Auger Lift Option Install
202L314	Pneg-1146	Hi-Cap 40 Grain Cleaner
206L0004	Pneg-1147	Hi-Cap 54 Grain Cleaner
602L011	Pneg-1148	Grain Flow - Model 84 w/ Dry Grain or Calc-U-Dri Cntrls
6027154	Pneg-1149	Grain Flow Bin Sweep
3077001	Pneg-1150	Gravity Flow Grain Spreader
4057013	Pneg-1151	Level Monitor III
5047047	Pneg-1152	Mc Printer
602L141	Pneg-1153	Calc-U-Dri Moisture/ Matic
602L142	Pneg-1154	Calc-U-Dri Moisture Monitor
1037016	Pneg-1155	Stir-Ator Parts Book 1965 to Present
106L001	Pneg-1156	Design III Series Grain Stir-Ator
OMDIICSA	Pneg-1157	Supplement to Design III Stir-Ator CSA Only
106N135 or 106N136	Pneg-1158	Design III Stir-Ator Stir Guard Option
	Pneg-1159	Kalke Murphy Stir -Ator
801L011	Pneg-1160	Trans-Fer 700, 1200, 1700, & 2100 Pneumatic Air System
280000-Man	Pneg-1161	Uni-Drive
		INTERNATIONAL
1067024	Pneg-1162	Design III Series Grain Stir-Ator
	Pneg-1163	Supplement to Design III Stir-Ators CSA only
106N135 or 106N136	Pneg-1164	Design III Stir-Ator Guard Option
2027318	Pneg-1165	Hi-Cap 40 Grain Cleaner
602N094	Pneg-1166	Grain Flow Model 76 to Model 84 Conversion Kit
6027152	Pneg-1167	Grain Flow-Model 84
3067005	Pneg-1168	Econo-Mizer Grain Spreader
8017029	Pneg-1169	Trans-Fer 700,1200,1700, & 2100 Pneumatic Air System
		INSTRUCTION SHEETS
47001	Pneg-1170	Airtube Install Sheet
8107005	Pneg-1171	Chain Loop Sys-Ground Cntrl Kit for Discharge Gate
5047072	Pneg-1172	Dryer Sampler Fuse Install
5047071	Pneg-1173	Dryer Sampler Instruction Sheet
103A0126	Pneg-1174	Stir-Ator Gooseneck & Swivel Replacement