	Terminal Description	Moisturematic Hookup	*Wire	GSI Dryer Hookup		
DC Volt Meter	SCR DC -	Terminal 1	Green	A-		
	SCR DC +	Terminal 2	Black	A+		
Speed Control	Slow End	Terminal 3	White/Yellow	J4-02		
	Wiper	Terminal 4	White/Red	SCR P2		
	Fast End	Terminal 5	Brown	J4-01		
115 VAC	110 VAC	L1	User Supplied	J6-01		
	110 Neutral	N	User Supplied	J6-02		
	110 Neutral	GND	User Supplied	GRND BLOCK		

Competitor Dryer

Network Dryer

	Terminal Description	Moisturematic Hookup	*Wire	GSI Dryer Hookup
DC Volt Meter	SCR DC -	Terminal 1	Green	J4-01
	SCR DC +	Terminal 2	Black	J4-02
Speed Control	Slow End	Terminal 3	White/Yellow	J3-06/SCRP1
	Wiper	Terminal 4	White/Red	SCR P2
	Fast End	Terminal 5	Brown	J3-13/SCRP3
115 VAC	110 VAC	L1	User Supplied	J8-19
	110 Neutral	N	User Supplied	J8-20
	110 Neutral	GND	User Supplied	GRND BLOCK

** PRE 1999

EMCS Drver

=				
	Terminal Description	Moisturematic Hookup	*Wire	GSI Dryer Hookup
DC Volt Meter	SCR DC -	Terminal 1	Green	A-
	SCR DC +	Terminal 2	Black	A+
Speed Control	Slow End	Terminal 3	White/Yellow	J6-01
	Wiper	Terminal 4	White/Red	SCR P2
	Fast End	Terminal 5	Brown	J6-04
115 VAC	110 VAC	L1	User Supplied	J9-05
	110 Neutral	N	User Supplied	J9-04
	110 Neutral	GND	User Supplied	GRND BLOCK

* 15 foot piece of 5 conductor cable that is included with moisture control

All GSI dryers made after 1999 will have 7 terminals designated for hookup with the moisture matic. These terminals will be located in the upper control box left hand side and are the 7 bottom terminals.

When connecting the speed control, disconnect the control wires and leave intact the wires running to the SCR board terminals P1, P2 and P3. This will disable the built in moisture control function of the GSI dryer.