




DISTRIBUTOR FOOT CONTROL


PART # DFB0443



DFB0443 - Distributor
foot control

Intallation recommendations:

1. Verify cable positioning so that there is no interference between the cable and steel when the foot control is actuated (See Figure 1 & Figure 2). Failure to do so can result in frayed cable.
2. Secure Distributor Foot Control assembly to floor using (2) 1/2" anchors (*not supplied*).
3. Run cable through the holes in the foot control as shown. Secure the cable in place by attaching two cable clamps to the cable on the underside of the foot control. (See Figure 1)



(2) Cable Clamps




Figure 1




Figure 2

Bill of Materials:

- (1) **DFB0439** - Base Weldment
- (1) **DFB0442** - Foot Lever Weldment
- (1) **S-6762** - Bolt HHCS 3/8-16 x 2-1/2"
- (1) **S-7383** - Nylock Nut 3/8-16
- (2) **S-8762** - Cable Clamp 3/16" (not shown)
- (1) **PNEG-1505** - Installation Recommendations